



Local Notice to Mariners 11 / 2025

Dis-establishment of Navigational Aid

Mariners are advised that Aberdeen Harbour Board have dis-established one of the single lit lateral buoys at Aberdeen South Harbour.

A statutory sanction has been received from the Commissioners of Northern Lighthouses and details are as follows:

Location description : Aberdeen South Harbour. No 1 Buoy.

Latitude : 57° 08.124' North (WGS-84 datum)

Longitude : 002° 02.428' West (WGS-84 datum)

Character : Fl (2) G 8s

Range : 5 miles

Colour/Shape : Green Conical

Topmark : Green Conical

This notice cancels and supersedes Notice No 08 of 2025

Port of Aberdeen
Marine Department
11th February 2025

Vessel Owners, Operators, Agents, Berth Operators etc should ensure that the contents of this Navigation Notice are made known to the Masters of their vessels.