



Local Notice to Mariners 17 / 2025

Aberdeen Fairway Buoy – AIS Signal Temporarily Unavailable

Mariners are advised that the AIS (Automatic Identification System) on the Aberdeen Fairway Buoy is currently inoperative.

The Buoy itself remains on station and exhibiting its normal light and physical characteristics, Mo(A)5s, but the AIS transmission is not currently being received at expected ranges offshore.

Mariners are reminded to navigate with caution in the approaches to Aberdeen Harbour and not to rely solely on electronic aids to navigation.

Port of Aberdeen
Marine Department
14th May 2025

Vessel Owners, Operators, Agents, Berth Operators etc should ensure that the contents of this Navigation Notice are made known to the Masters of their vessels.

Document	Title	Revision	Effective Date
PoA-MAR-FOR-003	Notice to Mariners	00	March 2025