

## Navigation Notice No 23 of 2023 Off Station Navigation Aids

Notice is hereby given that the following Navigation aids are off station.


Aberdeen Fairway Buoy, this buoy is currently in the approximate position indicated by the red dot

approximate position is 57-08.817N 002-04.367W  
The buoy is currently flashing with its usual rhythm.

Mariners are advised to the instructions from VTS and all port users are requested to keep well clear of the buoy.

Due to the complex recovery requirements of the buoy it may be in situ for a period exceeding 2 weeks due to the depths around the buoy

A replacement Fairway buoy is expected to be installed within the next 10 days



South Harbour Number 1 Green Lateral buoy is currently off station and will be repositioned within the next 2 weeks.

Alex McIntosh  
Harbour Master  
24<sup>th</sup> October 2023

Owners, Agents, Berth Operators etc should ensure that the contents of this Navigation Notice are made known to the Masters of their vessels.